```
Mauna Loa Solar Observatory Observer's Log
 ______
      Thu Jan 14 17:58:37 GMT 2021
Year: 21 Doy: 014
Observer: berkey
WEATHER COMMENT: berkey: Thu Jan 14 17:59:38 GMT 2021
Temp: 38.3f, Humidity: 13%, Pressure: 28.848in, Wind: 4mph from 167degs, Skies: mostly clear with bands of cirrus to the N
Ε
 end
GENERAL COMMENT BY berkey: Thu Jan 14 17:59:40 GMT 2021
Opened windows upstairs
 end
GENERAL COMMENT BY berkey: Thu Jan 14 17:59:44 GMT 2021
PM Blew off Kcor O1
 end
Thu Jan 14 18:19:57 GMT 2021 Kcor Focus/alignment program exited
Thu Jan 14 18:21:34 GMT 2021 KCOR Start Synoptic Patrol
Thu Jan 14 18:55:42 GMT 2021 KCOR End Patrol
Thu Jan 14 18:55:43 GMT 2021 KCOR Start Calibration script: c:\kcor\mlso-calibration22deg-20171025.ini
GENERAL COMMENT BY berkey: Thu Jan 14 18:57:04 GMT 2021
Power outage.
end
Thu Jan 14 19:10:57 GMT 2021 KCOR End Calibration Script
Thu Jan 14 19:11:14 GMT 2021 KCOR Start Synoptic Patrol
Thu Jan 14 19:11:14 GMT 2021 KCOR Start Synoptic Patrol
GENERAL COMMENT BY berkey: Thu Jan 14 19:14:47 GMT 2021
Looks like the outage may have only been our building. No UPS beeps on the NOAA buildings, and the lights in the NDACC bu
ilding work.
Cycling the lightening supression system seems to have brought the our main feed back online.
GENERAL COMMENT BY berkey: Thu Jan 14 19:18:10 GMT 2021
Dome covered KCor (maybe during the calibration). Looks like the new senor positions arent working.
GENERAL COMMENT BY berkey: Thu Jan 14 19:20:00 GMT 2021
Looks like we are down one electrical phase. The PSPT half of the building remains powered down.
end
Thu Jan 14 19:40:56 GMT 2021 Kcor Focus/alignment program exited
GENERAL COMMENT BY berkey: Thu Jan 14 19:47:22 GMT 2021
Dome sensors moved, to now not catch the trailing dome shutter edge and hopefully just the leading edge.
May still need some tweaking to find the best position.
end
GENERAL COMMENT BY berkey: Thu Jan 14 19:59:44 GMT 2021
Lost all power again.
end
GENERAL COMMENT BY berkey: Fri Jan 15 02:32:53 GMT 2021
```

During the power outage.

Inspected the RA drive train and found the RA clutch way too tight and we were slipping the drive train along the 2 big ro llers. This appears to have lead to some marring of the wheel surfaces.

Clutch was loosened to get the slipping back in the proper location. There isn't much range between too loose and too tig ht, so I think we need to move forward on clutch pad replacement.

More work was done on UCoMP to finish installing the calibration stage and cable up everything else in the box. Still ne ed to spend some time checking the occulter and calibration stage cables to see if they run smoothly over the range of the stage motion.

____end____

GENERAL PROBLEM COMMENT BY berkey: Fri Jan 15 02:37:04 GMT 2021

The Dome closure UPS appears to no longer hold a change, battery was dead when I went to close the dome.

By tempoarly rewiring the dome closure power cord with an L6-30 plug instead of an L6-20 plug I was able to close the dome via the MATRIX UPS. The only L6-30 plug I could find in the observatory was the plug used to power the Matrix UPS, so this is no a good long term fix.

I plan to build a short convert that we can plug into the end of the dome UPS cable to change its connector from the L6-20 to L6-30 so we could move back and forth between the 2 UPS's (assuming of course we replace the batteries in the Dome UPS).

___end___

GENERAL COMMENT BY berkey: Fri Jan 15 03:02:46 GMT 2021

Tried bringing up all the systems on UCoMP for some remote work over the next week, I found a burnt smell on the dome.

The smell seems to have to come from either the spar powersupply or piggyback plate. But I have no not been able to pin d own the source. But for now all 3 legs of the spar power supply are unplugged.

____end___

Fri Jan 15 03:39:01 GMT 2021 Kcor Focus/alignment program exited

ONSITE STAFF: berkey