

XEROX SECURITY BULLETIN XRX07-001

Vulnerabilities exist in the ESS/ Network Controller that, if exploited, could allow remote execution of arbitrary software, forgery of digital certificates or initiation of Denial of Service attacks.

The following software solution (patch P30) and self-service instructions are provided for the listed products. This patch is designed to be installed by the customer. Please follow the procedures below to install the patch to protect your device from possible attack through the network.

The software solution is compressed into a 990 KB zip file and can be accessed via the link below:

http://www.xerox.com/downloads/usa/en/c/cert_P30_ESS_Network_Controller_Patch.zip

Customers concerned about this vulnerability in the products listed below should first use the attached installation instructions to verify that they have the proper release to install the patch. For WC/WCP 2xx Series products, System Software Version *.60.22.000 or higher (ESS Controller Version 040.022.*1031 or higher) already contains this fix and the installation of the patch is not required.

Please read the installation instructions for the proper steps to take in case you are not at the release indicated above or higher for any of the affected products. In addition, for a WorkCentre® 7655/7665 if the System Software is not 040.032.53080 or above (Net Controller Version 040.022.*1031 or above), a service rep must be contacted to upgrade the machine to System Software/Net Controller Version 040.032.53080, before the patch can be applied.

Note: This security patch is designated as patch **P30**. Once this patch is successfully installed, the Network Controller version will display **.P30** (Ex. 40.010.#1172.P30). To reiterate again, for WC/WCP 2xx Series products, System Software Version *.60.22.000 or higher (ESS Controller Version 040.022.*1031 or higher) already contains this fix and the installation of the patch is not required.

Background

As part of Xerox's on-going efforts to protect customers, the following vulnerabilities documented in Red hat Security Advisory RHSA-2006:0695-12 against OpenSSL were discovered:

- Improper bounds-checking of user input
- Improper handling of error conditions
- Inadequate processing of digital signatures
- Improper validation of public key length
- Insecure peer-to-peer protocol negotiation

These vulnerabilities in the ESS/ Network Controller code could allow an attacker to bypass authentication and remotely execute arbitrary software, falsify credentials or initiate Denial of Service attacks against the device.

If successful, an attacker could make unauthorized changes to the system configuration. Customer and user passwords are not exposed.

Products This Patch Applies To:

WorkCentre®	WorkCentre® Pro
232	232
238	238
245	245
255	255
265	265
275	275
7655	
7665	

Solution

Install Instructions

Patch file name: **P30.dlm**

This patch can be installed to your systems as outlined below.

Summary of versions and actions:

- Determine starting System Software version or ESS Controller Version
- Determine what upgrades are necessary
- Upgrade devices as needed
- Apply the patch if needed

For WC/WCP 232/238/245/255/265/275

	If Your Software Version Is System SW or ESS Controller		Ready for Patch?	Next step:	Then:	Network Controller/ESS Will Now Show:
1	*.27.24.000 to *.27.24.020	040.010.#0930 to 040.010.#1160	Yes	Upgrade to *.60.22.000 or higher. See Appendix A	-	040.022.#1031
2	*.50.03.000 to *.50.03.009	040.010.#1172 to 040.010.#2250	Yes	Upgrade to *.60.22.000 or higher. See Appendix A	-	040.022.#1031
3	*.50.03.011	040.010.#2280	No	Call Service to upgrade to *.60.22.000 or higher	-	040.022.#1031
4	*.27.24.015 Common Criteria Certified	040.010.#1121	No	See NOTE 1 below	-	-
5	*.39.24.001 Common Criteria Certified	040.010.#1123	No	See NOTE 1 below	-	If patch is applied, 040.022.#0115.P30
6	*.60.15.000	040.022.#0112	No	Upgrade to *.60.22.000 or higher See Appendix A	-	040.022.#1031
7	*.60.17.000 Common Criteria Certified	040.022.#0115	Yes	See NOTE 2 below	-	If patch is applied, 040.022.#0115.P30
8	*.60.17.000 to *.60.17.006	040.022.#0115 to 040.022.#1022	Yes	Load patch P30 Or Upgrade to *.60.22.000 or higher. See Appendix A	-	040.022.#1031
9	*.60.17.008	040.022.#1031	N/A	done	-	-
10	*.60.22.000 and above	040.022.#1031	N/A	done	-	-

NOTE 1: If your device has a System Software version of either *.27.24.015 or *.39.24.001, then your device is in a Common Criteria certified configuration. You can upgrade to x.60.17.000 and then load the P30 patch (row 7 above), although the device would then no longer be in a Common Criteria certified configuration.

NOTE 2: If your device has a System Software version of *.60.17.000, then your device is in a **soon-to-be** Common Criteria certified configuration. You can load the P30 patch if desired, although the device would then no longer be in **the** Common Criteria certified configuration **once certification** has been completed.

For WC 7655/7665

	If Your Software Version Is System SW or Net Controller		Ready for Patch?	Next step:	Then:	Network Controller/ESS Will Now Show:
1	040.032.50855 to 040.032.51040	040.032.50855 to 040.032.51030	No	Call Service to Upgrade to 040.032.53080	Load P30 patch	040.032.53080.P30
2	040.032.53080	040.032.53080	Yes	Load P30 patch	-	040.032.53080.P30
3	040.032.53080 Common Criteria Certified	040.032.53080	Yes	See NOTE 1 below	-	If patch is applied, 040.032.53080.P30
4	040.032.55030 and above	040.032.55030 and above	N/A	done	-	-

NOTE 1: If your device has a System Software version of 040.032.53080, then your device is in a Common Criteria certified configuration. You can load the P30 patch (follow Row 2 above) if desired, although the device would then no longer be in a Common Criteria certified configuration.

Install the Patch

You must download the patch. The patch is packaged in a ZIP format. Download the ZIP file from the URL provided and extract all contents to your desktop. Do not try to open the file with the .DLM extension. This is the patch and must be loaded on the MFD as is.

Patch Installation Methods

This patch and upgrade (like most software) can and should be installed by the customer. There are a variety of methods available for this.

- Send an Upgrade / Patch file to the device using the device web page for Machine Software Upgrade method.
- Upgrade / Patch a single device using an LPR command.
- Upgrade / Patch several devices using a batch of LPR commands.
- Using XDM and CentreWare Web to send Upgrade / Patch files to several devices.

For additional information on the above methods refer to Customer Tip “How to Upgrade, Patch or Clone Xerox Multifunction Devices“ (<http://www.office.xerox.com/support/dctips/dc06cc0410.pdf>)

Machine Software (Upgrade) Method

- 1) Open a web browser and connect to the multifunction device by entering the IP number of the device.
- 2) Select the “Index” icon in the upper middle portion of the screen.
- 3) Select “Machine Software (Upgrades)”.
- 4) Enter the User Name and Password of the device.
- 5) Under “Manual Upgrade” select Browse button to find and select the file,P30.dlm.
- 6) Select the “Install Software” button.
- 7) All WCPs will print a patch install sheet and automatically reboot in order to install the patch. The patch is installed when .P30 is appended to the Network Controller (ESS) version number.

Appendix A

Obtaining System Software

To obtain system software versions *.60.22.000 or later:

- a) Use a browser to navigate to www.xerox.com.
- b) Select the link called "Support & Drivers".
- c) Select "Multifunction".
- d) Select "WorkCentre" or "WorkCentre Pro" depending on your model.
- e) Locate the link for your WorkCentre model.
- f) Select "Drivers & Downloads".
- g) Select the link for "Firmware & Machine Upgrades".
- h) Select the link for "System software set *.60.22.000 install instructions" and print or save these instructions.
- i) Select the link for "System Software set *.60.22.000" and save the file to your computer.
- j) Once downloaded, extract the files to your desktop.
- k) Review the "System Software Install Instructions" that you saved.
- l) Upgrade the device.

Disclaimer

The information in this Xerox Product Response is provided "as is" without warranty of any kind. Xerox Corporation disclaims all warranties, either express or implied, including the warranties of merchantability and fitness for a particular purpose. In no event shall Xerox Corporation be liable for any damages whatsoever resulting from user's use or disregard of the information provided in this Xerox Product Response including direct, indirect, incidental, consequential, loss of business profits or special damages, even if Xerox Corporation has been advised of the possibility of such damages. Some states do not allow the exclusion or limitation of liability for consequential damages so the foregoing limitation may not apply.