
Mauna Loa Solar Observatory Observer's Log

Mon Apr 6 17:04:15 GMT 2015

Year: 15 Doy: 096

Observer: berkey

WEATHER COMMENT: berkey: Mon Apr 6 17:04:17 GMT 2015

temp 41f, wind 5mph from the SE, skies are hazy with patches of cirrus .

____end____

Mon Apr 06 17:14:57 GMT 2015 COMP Start Patrol

Mon Apr 06 18:51:48 GMT 2015 COMP End Patrol

Mon Apr 06 20:53:14 GMT 2015 KCOR Start Synoptic Patrol

Mon Apr 06 21:13:04 GMT 2015 COMP Start Patrol

GENERAL OBSERVATORY COMMENT BY berkey: Mon Apr 6 21:19:53 GMT 2015

CMST updated the 2911 router to latest/recommened IOS.

____end____

Mon Apr 06 21:46:30 GMT 2015 KCOR End Patrol

Mon Apr 06 21:48:09 GMT 2015 CoMP Paused for clouds

Mon Apr 06 21:50:36 GMT 2015 CoMP Restarted from pause

Mon Apr 06 21:51:40 GMT 2015 KCOR Start Synoptic Patrol

Mon Apr 06 21:59:19 GMT 2015 KCOR End Patrol

Mon Apr 06 22:02:17 GMT 2015 KCOR Start Synoptic Patrol

Mon Apr 06 22:27:10 GMT 2015 KCOR End Patrol

Mon Apr 06 22:27:50 GMT 2015 CoMP Paused for clouds

Mon Apr 06 22:31:45 GMT 2015 KCOR Start Synoptic Patrol

Mon Apr 06 22:31:50 GMT 2015 CoMP Restarted from pause

GENERAL OBSERVATORY COMMENT BY berkey: Mon Apr 6 22:54:17 GMT 2015

Large flare from erupting from sunspot group 2320 at around 19:20UT

____end____

Mon Apr 06 23:08:25 GMT 2015 KCOR End Patrol

Mon Apr 06 23:08:48 GMT 2015 CoMP Paused for clouds

Mon Apr 06 23:28:06 GMT 2015 CoMP Restarted from pause

Mon Apr 06 23:28:06 GMT 2015 COMP End Patrol

GENERAL OBSERVATORY COMMENT BY berkey: Tue Apr 7 01:53:40 GMT 2015

Some ACLs were installed on the router to limit the the protocols allowed to connectd in. As far as I can tell the ACL's don't cause any problems with our operations.

____end____

GENERAL OBSERVATORY COMMENT BY berkey: Tue Apr 7 02:17:55 GMT 2015

took advantage of the clouds and fog to do some dome shutter maintance. Rollers and tracks lubbed. Pspt seems to be running a lot smoother, there is still a little bit of noise in the middle of its range. On the main dome one roller was replaced, I think the slight bend in the shutter roller tracks is eating up the rollers. We are also now out of spare rollers again. Even with the luburcation the main dome still doesn't move as smoothly as PSPT. But this should be good enough for the next few months and hopefully the new dome gets installed sooooooner then later.

____end____