Mauna Loa Solar Observatory Observer's Log ______ Mon May 14 15:55:02 GMT 2018 Year: 18 Doy: 134 Observer: waters WEATHER COMMENT: waters: Mon May 14 16:14:09 GMT 2018 Temp 39F with windspeed at about 8-15mph from the Southwest. Vog is at about 8,000ft. Sky is clear but it looks incredibly bright at the moment. end GENERAL COMMENT BY waters: Mon May 14 16:23:08 GMT 2018 PM Blew off Kcor O1 end Mon May 14 16:52:36 GMT 2018 Kcor Focus/alignment program exited Mon May 14 16:56:14 GMT 2018 KCOR Start Synoptic Patrol GENERAL OBSERVATORY COMMENT BY waters: Mon May 14 17:48:34 GMT 2018 Spent the last hour trying to figure out why Shabar wasn't working. I tried unplugging and replugging the usb in the compu ter, I cleaned the usb and usb port on shabar and checked the wires/switches. Normally when you disconnect and reconnect t he USB a screen pops up saying that a device was detected but when I replugged it in, it didn't show up. I tried the right usb port but the usb was too loose in it. Plugged it back into the left usb port on the laptop and nothing happened. But after a while a prompt came up saying the usb was corrupt and therefore the computer couldn't see it. I checked the right usb port and jiggled it around and I got it to read the usb for a bit but then it couldn't. Found a port on the back of th e laptop and it installed the software to use the usb. After that, it was a matter of getting the shabar.vi to work. After restarting the program, everything seems to be working now. end Mon May 14 19:07:46 GMT 2018 SGS Alignment complete Mon May 14 22:43:54 GMT 2018 KCOR End Patrol GENERAL OBSERVATORY COMMENT BY waters: Mon May 14 22:47:52 GMT 2018 Clouds have come up from Saddle and look like they might stay awhile. Instruments idled. end GENERAL OBSERVATORY COMMENT BY waters: Mon May 14 22:52:43 GMT 2018 Taking this time to take another look at the field. end GENERAL OBSERVATORY COMMENT BY waters: Mon May 14 23:28:13 GMT 2018 Took a look at the field lens and camera 1. Nothing unusual seemed to be a miss with camera on, although the tap was comin q up from the Lyot stop. Field lens had some visible dust on it that would not be blown off to the side on the South-South east area. This may be the spots we are seeing but it's hard to tell. Did not remove the field lens but since I had the ba ck end cover off, I blew off the back side of the field lens as well. GENERAL OBSERVATORY COMMENT BY waters: Mon May 14 23:31:45 GMT 2018 SGS Home Dec is having trouble again.

ONSITE STAFF: waters