

**MERCURY MARINE**

(Fond du Lac, WI)(000077T)

Year: 2000

Models: MerCruiser inboards and  
sterndrives:

MCM 4.3L w/ serial nos.:

0L647917 - 0L658366

MCM 4.3L w/ serial nos.:

0L654815 - 0L658152

MCM 5.0L w/ serial nos.:

0L654187 - 0L658223

MCM 5.7L w/ serial nos.:

0L654116 - 0L658145

MCM 5.7L w/ serial nos.:

0L654602 - 0L658145

MCM 350 MAG MPI w/ serial nos.:

0L654350 - 0L656214

MCM 7.4L MPI w/ serial nos.:

0L644495 - 0L655222

MCM 454 MAG MPI w/ serial nos.:

0L604282 - 0L632796

MCM 502 MAG MPI w/ serial nos.:

0L632682 - 0L632764

MIE 5.7L w/ serial nos.:

0L393670 - 0L395314

MIE 350 MAG MPI w/ serial nos.:

0L395246 - 0L396029

MIE 7.4L MPI w/ serial nos.:

0L395656 - 0L395724

MIE 454 MAG MPI w/ serial nos.:

0L395915 - 0L396234

MIE 8.2L MPI w/ serial nos.:

0L395753 - 0L395767

Units: 2,108

Problem: Stainless steel electric fuel pump  
could crack causing fuel leakage; possible  
fire/explosion if ignition source present

**MERCURY MARINE**

(Fond du Lac, WI)(990173T)

Year: 1998 and 1999

Models: Mercury and Mariner 225/250 HP,  
3.0 Litre (Carb/EFI) XL, CXL, XXL  
and CXXL

3.0 Litre (OptiMax) XL, CXL, XXL  
and CXXL with serial nos.:

0G644802 thru 0G870075

Units: 6,830

Problem: Steering arm attaching bolt may  
fail; possible loss of steering control

**MERCURY MARINE**

(Fond du Lac, WI)(000078T)

Year: 1999

Models: MerCruiser High Performance

900 SC engines w/ serial nos.:

0L640007 and below

Units: 57

Problem: Fuel line between fuel filter and  
carburetors could crack causing fuel leakage;  
possible fire/explosion if ignition source  
present

**PRO-LINE BOATS**

(Crystal River, FL)(990192T)

Year: 2000

Models: All boats with breaker box  
manufactured by ESI South, Inc.

Units: 147

Problem: Breaker box may contain non  
ignition-protected circuit breakers; possible  
fire/explosion if fuel or vapor source present

**PURSUIT/S2 YACHTS, INC.**

(Fort Pierce, FL)(000106S)

Year: 2000

Models: 2260 Denali w/ HINs:

SSUF2099G900 - SSUF2107K900

2460 Denali w/ HINs:

SSUF4362F900 - SSUF439IL900

Units: 39

Problem: Blower warning label missing