3.5.1.1	D 11	3.6.1.1.001		- 1D	0.1	D.C.	· ·
Method	Pollutant	Method 301	Other Validation	External Peer	Other	References	Comments/
Name	Measured	Validation		Review/	External		Contact Person
				Internal EPA	Review		
				Peer Review			
Guide	Ambient	yes		External and	AWMA		Dan Bivins (this
for	metals			internal	Paper		is a guide for
Developi							using Multi- metals method)
ng a							metais memou)
Multi-							
Metals,							
Fence-							
Line							
Monitor							
ing Plan							
for							
Fugitive							
Emissio							
ns Using							
X-Ray							
Based							
Monitor							
S							