
Mauna Loa Solar Observatory Observer's Log

Sat Sep 23 16:53:47 GMT 2000

Year: 00 Doy: 267

Observer: koon

Sat Sep 23 16:54:43 GMT 2000 CHIP Startup--Initializing new tape

Sat Sep 23 16:57:43 GMT 2000 MKIV Start Patrol

Sat Sep 23 16:57:53 GMT 2000 CHIP CHIP Start 7 Passband Patrol

Sat Sep 23 16:57:58 GMT 2000 PICS Start Patrol

Sat Sep 23 18:03:14 GMT 2000 PICS Flat

Sat Sep 23 18:06:56 GMT 2000 PICS End Flat

MKIV PROBLEM : Sat Sep 23 18:56:23 GMT 2000

It looks like the tape only got 2 or 3 files yesterday before the writing stopped
There was a Media error message on the screen this morning. I'll toss the tape
and write the files to a new tape.

WEATHER COMMENT: Sat Sep 23 18:58:30 GMT 2000

Forgot to include this earlier, at 7 am the wind=5 mph from the SE, temp=47 F,
sky was and still is clear.

Sat Sep 23 20:01:38 GMT 2000 CHIP Gain7

Sat Sep 23 20:10:01 GMT 2000 CHIP End Gain

Sat Sep 23 20:10:18 GMT 2000 CHIP Bias

Sat Sep 23 20:11:25 GMT 2000 CHIP End Bias

MLSO PROBLEM : Sat Sep 23 20:12:28 GMT 2000

Pausing instruments while I do some work on the dome shutter binding problem.

Sat Sep 23 20:15:31 GMT 2000 CHIP CHIP End Patrol

Sat Sep 23 20:16:43 GMT 2000 PICS End Patrol

Sat Sep 23 20:37:58 GMT 2000 MKIV Start Patrol

Sat Sep 23 20:38:21 GMT 2000 CHIP CHIP Start 7 Passband Patrol

Sat Sep 23 20:38:34 GMT 2000 PICS Start Patrol

MLSO PROBLEM : Sat Sep 23 20:43:22 GMT 2000

I removed the worn shutter rack guide and will figure the best way to replace
it, for now we must avoid opening the dome beyond 1 foot from the fully opened
position to avoid the gear jumping out of the track. It is obvious that the
shutter is warped compare to the dome, it is twisted slightly and the radius
of curvature is greater than the dome. There is reference to "fixing the
warped dome" in some old dome related papers, maybe the fixing never happened.
Anyway, we should be OK with a new L-bracket shaped guide.

COMMENT: Sat Sep 23 20:47:30 GMT 2000

Extended the dome slot.

MKIV PROBLEM : Sat Sep 23 20:47:44 GMT 2000

I got the data from d266 to tape, I kept getting "tape write errors" so it
took 3 tries using the same tape.

WEATHER COMMENT: Sat Sep 23 21:36:55 GMT 2000

Medium cirrostratus has moved in, closing down to go vote.

Sat Sep 23 21:38:17 GMT 2000 CHIP CHIP End Patrol

Sat Sep 23 21:38:44 GMT 2000 PICS End Patrol

Sat Sep 23 21:41:28 GMT 2000 CHIP ending tape

COMMENT: Sat Sep 23 21:52:45 GMT 2000

TAPES:

MKIV: 00-267

CHIP: C01228

PICS: P01847

LOWL: Being upgraded.

Sat Sep 23 21:54:10 GMT 2000

MkIV

16_57.rawmk4	17_51.rawmk4	18_55.rawmk4	19_49.rawmk4	21_04.rawmk4
17_00.rawmk4	17_54.rawmk4	18_58.rawmk4	19_52.rawmk4	21_07.rawmk4
17_03.rawmk4	17_57.rawmk4	19_01.rawmk4	19_55.rawmk4	21_10.rawmk4
17_06.rawmk4	18_00.rawmk4	19_04.rawmk4	19_59.rawmk4	21_13.rawmk4
17_09.rawmk4	18_03.rawmk4	19_07.rawmk4	20_02.rawmk4	21_16.rawmk4
17_12.rawmk4	18_06.rawmk4	19_10.rawmk4	20_05.rawmk4	21_19.rawmk4
17_15.rawmk4	18_09.rawmk4	19_13.rawmk4	20_07.rawmk4	21_22.rawmk4
17_18.rawmk4	18_12.rawmk4	19_16.rawmk4	20_10.rawmk4	21_25.rawmk4
17_21.rawmk4	18_18.rawmk4	19_19.rawmk4	20_13.rawmk4	21_28.rawmk4
17_24.rawmk4	18_25.rawmk4	19_22.rawmk4	20_37.rawmk4	21_31.rawmk4
17_27.rawmk4	18_31.rawmk4	19_25.rawmk4	20_40.rawmk4	21_34.rawmk4
17_30.rawmk4	18_34.rawmk4	19_28.rawmk4	20_43.rawmk4	c18_15.rawmk4
17_33.rawmk4	18_37.rawmk4	19_31.rawmk4	20_46.rawmk4	c18_22.rawmk4
17_36.rawmk4	18_40.rawmk4	19_34.rawmk4	20_49.rawmk4	c18_28.rawmk4
17_39.rawmk4	18_43.rawmk4	19_37.rawmk4	20_52.rawmk4	
17_42.rawmk4	18_46.rawmk4	19_40.rawmk4	20_55.rawmk4	
17_45.rawmk4	18_49.rawmk4	19_43.rawmk4	20_58.rawmk4	
17_48.rawmk4	18_52.rawmk4	19_46.rawmk4	21_01.rawmk4	