\_\_\_\_\_\_

## Mauna Loa Solar Observatory Observer's Log

\_\_\_\_\_

Thu Dec 13 17:19:46 GMT 2001

Year: 01 Doy: 347

Observer: koon

WEATHER COMMENT: Thu Dec 13 17:19:50 GMT 2001

Snowing and raining, 1-2" of snow on ground, luckily the rain is keeping the

ice away so I could drive all the way up - barely.

COMMENT: Thu Dec 13 17:20:51 GMT 2001

Placed buckets under the roof leaks. It looks like the power hasn't been

interrupted yet.

WEATHER COMMENT: Thu Dec 13 21:50:07 GMT 2001

Snowing all day.

\*\*PICS PROBLEM\*\*: Thu Dec 13 21:50:17 GMT 2001

I swapped the  ${\tt HOME\_NC}$  and  ${\tt HOME\_NO}$  wires before the assembly side connector.

This fixed the reverse-Home problem, hopefully it will help with the timeout

problems we sometimes see.

PICS COMMENT: Thu Dec 13 22:03:24 GMT 2001

PICS is back together and ready to use.

Thu Dec 13 22:18:05 GMT 2001

MkIV