
Mauna Loa Solar Observatory Observer's Log

Wed Aug 2 16:26:49 GMT 2006

Year: 06 Doy: 214

Observer: yasukawa

WEATHER COMMENT: Wed Aug 2 16:27:59 GMT 2006

Clear, SW wind 11 mph, temp 40 F.

____end____

MKIV COMMENT: Wed Aug 2 16:28:36 GMT 2006

Turned KCC on, checked Synchro system power supply and 5V supply was at 1.5 V as it has been for the last few days. Turned on bench power supply paralleled with it and boosted power back up to 5.02 V. Startup proceeded normally, barrel rotated from 359 to 176 degrees as it should.

____end____

Wed Aug 2 16:34:41 GMT 2006 CHIP Start Patrol

Wed Aug 2 16:34:51 GMT 2006 PICS Start Patrol

SBM COMMENT: Wed Aug 2 16:35:04 GMT 2006

Observing.

____end____

PSPT COMMENT: Wed Aug 2 16:36:22 GMT 2006

Start up.

____end____

PSPT COMMENT: Wed Aug 2 16:44:52 GMT 2006

Observing.

____end____

Wed Aug 2 16:53:34 GMT 2006 MKIV Start Patrol

COMMENT: Wed Aug 2 17:06:06 GMT 2006

Replaced system lithium battery in iiwi.

____end____

MKIV PROBLEM: Wed Aug 2 17:36:37 GMT 2006

Flipped off auxiliary bench power supply briefly during barrel turnaround to check if the Semiconductor Circuits ps is back up at 5V. It is still at 1.5V. That glitch caused barrel to rotate in the wrong direction and rotate to the CCW limit at low speed (30). Stopped barrel with gui button and selected 240 in CW direction to get Patrol going again.

____end____

PSPT PROBLEM: Wed Aug 2 17:42:33 GMT 2006

Crashed at 1724 Ut, k/r

____end____

MKIV PROBLEM: Wed Aug 2 17:54:57 GMT 2006

Checked SC power, still low. Manually fixed scan glitch caused by interruption.

____end____

Wed Aug 2 17:59:13 GMT 2006 MKIV End Patrol

Wed Aug 2 17:59:19 GMT 2006 MKIV Start Cal

Wed Aug 2 18:01:44 GMT 2006 CHIP LSD

Wed Aug 2 18:02:16 GMT 2006 PICS Flat

```

Wed Aug  2 18:03:32 GMT 2006    CHIP    End LSD
Wed Aug  2 18:03:41 GMT 2006    CHIP    BiasLSD
Wed Aug  2 18:04:22 GMT 2006    CHIP    End BiasLSD
Wed Aug  2 18:04:30 GMT 2006    CHIP    Bias
Wed Aug  2 18:04:47 GMT 2006    PICS    End Flat
Wed Aug  2 18:04:54 GMT 2006    PICS    ReStart Patrol
Wed Aug  2 18:05:12 GMT 2006    CHIP    End Bias
Wed Aug  2 18:05:27 GMT 2006    CHIP    ReStart Patrol
Wed Aug  2 18:15:44 GMT 2006    MKIV    End Cal
Wed Aug  2 18:15:51 GMT 2006    MKIV    Start Patrol
**MKIV PROBLEM**: Wed Aug  2 18:16:30 GMT 2006
SC ps still not recovered.
__end__
NICE MK4      IMAGE: 1802
NICE CHIP     IMAGE: 1801
NICE PICSLIMB IMAGE: 1802
NICE PICSDISC IMAGE: 1801
Wed Aug  2 18:20:53 GMT 2006    MKIV    End Patrol
**MKIV PROBLEM**: Wed Aug  2 18:24:56 GMT 2006
Stopped scan to check SC 5V output.  It is still at 1.5V.
__end__
Wed Aug  2 18:25:35 GMT 2006    MKIV    Start Patrol
Wed Aug  2 19:02:23 GMT 2006    MKIV    Start Patrol
MKIV COMMENT: Wed Aug  2 19:01:39 GMT 2006
SC power supply now providing 5V on its own.  Turned off auxiliary bench
power supply.
__end__
Wed Aug  2 19:36:00 GMT 2006    CHIP    End Patrol
Wed Aug  2 19:36:20 GMT 2006    PICS    End Patrol
Wed Aug  2 19:37:54 GMT 2006    MKIV    End Patrol
Wed Aug  2 19:42:08 GMT 2006    MKIV    Start Patrol
COMMENT: Wed Aug  2 19:42:24 GMT 2006
Reconfigured dome shutter.
__end__
Wed Aug  2 19:42:30 GMT 2006    CHIP    Start Patrol
Wed Aug  2 19:42:35 GMT 2006    PICS    Start Patrol
Wed Aug  2 21:57:31 GMT 2006    MKIV    End Patrol
Wed Aug  2 21:58:00 GMT 2006    CHIP    End Patrol
Wed Aug  2 21:58:40 GMT 2006    PICS    End Patrol
Wed Aug  2 22:03:58 GMT 2006
MkIV

16_53.rawmk4  18_02.rawmk4  19_11.rawmk4  20_14.rawmk4  21_13.rawmk4
16_56.rawmk4  18_08.rawmk4  19_14.rawmk4  20_17.rawmk4  21_16.rawmk4
16_59.rawmk4  18_14.rawmk4  19_17.rawmk4  20_20.rawmk4  21_19.rawmk4
17_02.rawmk4  18_15.rawmk4  19_20.rawmk4  20_23.rawmk4  21_22.rawmk4
17_05.rawmk4  18_17.rawmk4  19_22.rawmk4  20_26.rawmk4  21_25.rawmk4
17_08.rawmk4  18_25.rawmk4  19_25.rawmk4  20_29.rawmk4  21_27.rawmk4

```

17_11.rawmk4	18_28.rawmk4	19_28.rawmk4	20_32.rawmk4	21_30.rawmk4
17_14.rawmk4	18_31.rawmk4	19_31.rawmk4	20_35.rawmk4	21_33.rawmk4
17_17.rawmk4	18_34.rawmk4	19_34.rawmk4	20_38.rawmk4	21_36.rawmk4
17_20.rawmk4	18_37.rawmk4	19_42.rawmk4	20_40.rawmk4	21_39.rawmk4
17_23.rawmk4	18_40.rawmk4	19_45.rawmk4	20_43.rawmk4	21_42.rawmk4
17_26.rawmk4	18_43.rawmk4	19_48.rawmk4	20_46.rawmk4	21_45.rawmk4
17_28.rawmk4	18_46.rawmk4	19_50.rawmk4	20_49.rawmk4	21_48.rawmk4
17_31.rawmk4	18_49.rawmk4	19_53.rawmk4	20_52.rawmk4	21_51.rawmk4
17_39.rawmk4	18_52.rawmk4	19_56.rawmk4	20_55.rawmk4	21_54.rawmk4
17_42.rawmk4	18_54.rawmk4	19_59.rawmk4	20_58.rawmk4	c17_59.rawmk4
17_45.rawmk4	18_57.rawmk4	20_02.rawmk4	21_01.rawmk4	c18_05.rawmk4
17_48.rawmk4	19_02.rawmk4	20_05.rawmk4	21_04.rawmk4	c18_11.rawmk4
17_51.rawmk4	19_05.rawmk4	20_08.rawmk4	21_07.rawmk4	
17_54.rawmk4	19_08.rawmk4	20_11.rawmk4	21_10.rawmk4	