

-----  
Mauna Loa Solar Observatory Observer's Log  
-----

Fri Mar 6 17:27:55 GMT 2009

Year: 09 Doy: 065

Observer: koon

WEATHER COMMENT: Fri Mar 6 17:27:58 GMT 2009

Foggy,cloudy, wind=2mph from the East, temp=40F.

\_\_\_\_end\_\_\_\_

COMMENT: Fri Mar 6 17:28:55 GMT 2009

Received 4 boxes of spare sparcstations from Boulder. Also got back our  
Observer's Manual from Boulder, put it back on shelf.

\_\_\_\_end\_\_\_\_

WEATHER COMMENT: Sat Mar 7 00:18:26 GMT 2009

Rainy/Foggy all day.

\_\_\_\_end\_\_\_\_

**\*\*MKIV PROBLEM\*\***: Sat Mar 7 00:18:39 GMT 2009

The EXSYNC camera timing signal isn't getting out of the transformation board  
and going to the camera, EXSYNCB side of the differential signal is there.

All +/-5 and +/-15 volt power to camera is good. Bad line driver(s)?

\_\_\_\_end\_\_\_\_

Sat Mar 7 01:00:55 GMT 2009

MkIV