```
Mauna Loa Solar Observatory Observer's Log
 ______
       Wed Nov 2 16:23:14 GMT 2016
Year: 16 Doy: 307
Observer: berkey
WEATHER COMMENT: berkey: Wed Nov 02 16:23:18 GMT 2016
Temp: 39.3f, Humidity: 9%, Pressure: 28.752in, Wind: 7mph from 148degs, Skies: clear
  end
Wed Nov 02 17:27:47 GMT 2016 SGS Alignment complete
Wed Nov 02 17:27:56 GMT 2016 CoMP occulter has been re-centered
Wed Nov 02 17:34:38 GMT 2016 COMP Start Patrol on cookbook: synoptic-00007.cbk
Wed Nov 02 17:36:22 GMT 2016 Kcor Focus/alignment program exited
Wed Nov 02 17:39:39 GMT 2016 KCOR Start Synoptic Patrol
KCOR COMMENT BY berkey: Wed Nov 02 17:51:03 GMT 2016
Kcor still has spots. The field lens will be pulled for cleaning.
  end
Wed Nov 02 17:54:50 GMT 2016 KCOR End Patrol
Wed Nov 02 19:14:38 GMT 2016 COMP End Patrol
Wed Nov 02 19:25:30 GMT 2016 SGS Alignment complete
Wed Nov 02 19:25:42 GMT 2016 CoMP occulter has been re-centered
Wed Nov 02 19:25:44 GMT 2016 COMP Start Patrol on cookbook: synoptic-00007.cbk
Wed Nov 02 19:26:55 GMT 2016 Kcor Focus/alignment program exited
KCOR COMMENT BY berkey: Wed Nov 02 19:34:36 GMT 2016
Field Lens cleaned. This cleared up the artifacts in the inner field. I am a little worried about the general level of res
idue in the outer field. Right now I am not really sure how to completely clean it.
The planned future upgrade to the lens cell should help, may making it easier/safter to hold the lens during washing. But
it seems like it would be nice if we could just take the lens and put it in some kind of bath overnight to clean/lift off
any residude.
 end
KCOR COMMENT BY berkey: Wed Nov 02 19:38:45 GMT 2016
The Kcor lens/occulter may not have gone into the telescope in the exacty same orientation as it came out. Visual inspec
tions suggested the cell/occulter were installed correctly. But during the sgs alignment I found there was a slightly big
ger then expected misalignment to comp.
 end
Wed Nov 02 19:38:55 GMT 2016 KCOR Start Synoptic Patrol
CME Alert BY berkey: Wed Nov 02 19:59:15 GMT 2016
Possible CME seen launching near PA: 270 around 18:00UT
  end
Wed Nov 02 22:05:59 GMT 2016 KCOR End Patrol
Wed Nov 02 22:06:29 GMT 2016 COMP End Patrol
Wed Nov 02 22:09:44 GMT 2016 SGS Alignment complete
Wed Nov 02 22:10:17 GMT 2016 CoMP occulter has been re-centered
Wed Nov 02 22:10:27 GMT 2016 COMP Start Patrol on cookbook: synoptic-00007.cbk
Wed Nov 02 22:12:59 GMT 2016 Kcor Focus/alignment program exited
```

Wed Nov 02 22:16:09 GMT 2016 KCOR Start Synoptic Patrol

Thu Nov 03 00:02:35 GMT 2016 KCOR End Patrol

Thu Nov 03 00:02:36 GMT 2016 KCOR Start Calibration script: c:\kcor\mlso-calibration22deq-20150323.ini GENERAL COMMENT BY berkey: Thu Nov 03 00:03:17 GMT 2016 held off on kcor calibration to see how the activity on the west limb evolved but with no obvious activity running the cal s now. ____end Thu Nov 03 00:19:51 GMT 2016 KCOR End Calibration Script Thu Nov 03 00:20:08 GMT 2016 KCOR Start Synoptic Patrol Thu Nov 03 00:20:08 GMT 2016 KCOR Start Synoptic Patrol Thu Nov 03 00:49:39 GMT 2016 KCOR End Patrol Thu Nov 03 00:50:03 GMT 2016 COMP End Patrol GENERAL COMMENT BY berkey: Thu Nov 03 00:50:15 GMT 2016 Comp camera is warming up Stoping observations for cryo fills end Thu Nov 03 01:09:13 GMT 2016 KCOR Start Synoptic Patrol Thu Nov 03 01:16:27 GMT 2016 CoMP occulter has been re-centered Thu Nov 03 01:17:00 GMT 2016 CoMP occulter has been re-centered Thu Nov 03 01:18:16 GMT 2016 CoMP occulter has been re-centered Thu Nov 03 01:18:17 GMT 2016 COMP Start Patrol on cookbook: synoptic-00007.cbk **COMP PROBLEM COMMENT BY berkey** : Thu Nov 03 01:29:56 GMT 2016 Sounds like one of the board fans in the ESP3000 is going out again.

___end___

Thu Nov 03 03:22:44 GMT 2016 KCOR End Patrol Thu Nov 03 03:23:14 GMT 2016 COMP End Patrol