
Mauna Loa Solar Observatory Observer's Log

Wed Feb 5 17:55:53 GMT 2020

Year: 20 Doy: 036

Observer: berkey

WEATHER COMMENT: berkey: Wed Feb 05 17:56:54 GMT 2020

Temp: 42.3f, Humidity: 8%, Pressure: 28.705in, Wind: 9mph from 211degs, Skies: clear

____end____

GENERAL COMMENT BY berkey: Wed Feb 05 17:56:58 GMT 2020

PM Washed Kcor 01

____end____

GENERAL COMMENT BY berkey: Wed Feb 05 17:57:06 GMT 2020

opened windows up stiaars

____end____

Wed Feb 05 18:01:09 GMT 2020 SGS Alignment complete

Wed Feb 05 18:04:36 GMT 2020 Kcor Focus/alignment program exited

Wed Feb 05 18:16:33 GMT 2020 KCOR Start Synoptic Patrol

Wed Feb 05 19:18:41 GMT 2020 KCOR End Patrol

Wed Feb 05 19:18:41 GMT 2020 KCOR Start Calibration script: c:\kcor\mlso-calibration22deg-20171025.ini

Wed Feb 05 19:33:56 GMT 2020 KCOR End Calibration Script

Wed Feb 05 19:34:12 GMT 2020 KCOR Start Synoptic Patrol

Wed Feb 05 19:34:13 GMT 2020 KCOR Start Synoptic Patrol

Wed Feb 05 20:33:26 GMT 2020 KCOR End Patrol

Wed Feb 05 20:34:56 GMT 2020 Kcor Focus/alignment program exited

Wed Feb 05 20:37:53 GMT 2020 Kcor Focus/alignment program exited

Wed Feb 05 20:38:09 GMT 2020 KCOR Start Synoptic Patrol

GPS COMMENT by MLSO: Wed Feb 05 21:45:06 GMT 2020

Successfully logged in to system

Good disk mount

GPS software running

Last 5 GPS data files are:

dataoutiq_2020_031_2226.bin 2147483647

dataoutiq_2020_032_2226.bin 2147483647

dataoutiq_2020_033_2226.bin 2147483647

dataoutiq_2020_034_2226.bin 2147483647

dataoutiq_2020_035_2226.bin 2147483647

____end____

Wed Feb 05 22:57:17 GMT 2020 KCOR End Patrol

Wed Feb 05 22:57:30 GMT 2020 KCOR End Patrol

GENERAL COMMENT BY berkey: Thu Feb 06 01:59:07 GMT 2020

Moved AED from the cabinets behind the racks, to now sit right next to the north double doors.

____end____

GENERAL COMMENT BY berkey: Thu Feb 06 02:03:33 GMT 2020

Made a small change to the sendToday script that triggers emailing out the daylog as well as a lot of other actions that copy and otherwise move the daylog around the various computers in Hawaii and Boulder.

We now strip the unprintable ascii character "005" from the log before sending it out. Looks like this character gets into

the log from time to time which screws up some processing scripts back in Boudler.
____end____

GONG COMMENT BY berkey: Thu Feb 06 02:06:15 GMT 2020

Swapped the gong UPS logic board per request from Gong_ops

____end____

ONSITE STAFF: berkey