```
Mauna Loa Solar Observatory Observer's Log
 ______
      Wed Dec 30 17:53:55 GMT 2020
Year: 20 Doy: 365
Observer: berkey
WEATHER COMMENT: berkey: Wed Dec 30 17:54:53 GMT 2020
Temp: 38.6f, Humidity: 20%, Pressure: 28.815in, Wind: 18mph from 112degs, Skies: clear
  end
GENERAL COMMENT BY berkey: Wed Dec 30 18:00:07 GMT 2020
Opened windows upstairs
end
GENERAL COMMENT BY berkey: Wed Dec 30 18:00:13 GMT 2020
PM Blew off Kcor O1
end
Wed Dec 30 18:08:31 GMT 2020 Kcor Focus/alignment program exited
Wed Dec 30 18:10:05 GMT 2020 KCOR Start Synoptic Patrol
Wed Dec 30 18:52:41 GMT 2020 KCOR End Patrol
Wed Dec 30 18:52:42 GMT 2020 KCOR Start Calibration script: c:\kcor\mlso-calibration22deg-20171025.ini
Wed Dec 30 19:07:57 GMT 2020 KCOR End Calibration Script
Wed Dec 30 19:08:13 GMT 2020 KCOR Start Synoptic Patrol
Wed Dec 30 19:08:14 GMT 2020 KCOR Start Synoptic Patrol
Wed Dec 30 19:28:14 GMT 2020 KCOR End Patrol
Wed Dec 30 19:31:16 GMT 2020 SGS Alignment complete
Wed Dec 30 19:31:17 GMT 2020 Kcor Focus/alignment program exited
Wed Dec 30 19:32:55 GMT 2020 KCOR Start Synoptic Patrol
Wed Dec 30 19:57:41 GMT 2020 KCOR End Patrol
Wed Dec 30 19:57:52 GMT 2020 KCOR Start Synoptic Patrol
Wed Dec 30 19:57:53 GMT 2020 KCOR End Patrol
Wed Dec 30 20:06:04 GMT 2020 KCOR Start Synoptic Patrol
Wed Dec 30 20:58:01 GMT 2020 KCOR End Patrol
Wed Dec 30 20:59:05 GMT 2020 SGS Alignment complete
Wed Dec 30 21:00:47 GMT 2020 Kcor Focus/alignment program exited
Wed Dec 30 21:09:58 GMT 2020 KCOR Start Synoptic Patrol
Wed Dec 30 21:34:24 GMT 2020 KCOR End Patrol
Wed Dec 30 21:34:27 GMT 2020 KCOR End Patrol
Wed Dec 30 21:37:59 GMT 2020 KCOR Start Synoptic Patrol
GENERAL COMMENT BY berkey: Wed Dec 30 22:11:28 GMT 2020
pausing observing for ucomp work
end
Wed Dec 30 22:11:34 GMT 2020 KCOR End Patrol
Wed Dec 30 22:11:37 GMT 2020 KCOR End Patrol
GENERAL COMMENT BY berkey: Thu Dec 31 01:38:35 GMT 2020
PM Blew off Kcor Field Lens
Thu Dec 31 01:42:23 GMT 2020 Kcor Focus/alignment program exited
GENERAL COMMENT BY berkey: Thu Dec 31 01:49:13 GMT 2020
Bessel beam laser power cable fell into the SGS beam. This dropped the SGSDIM down to ~4V vs the 6.6 it should be.
```

Wire is clear now.

___end___

GENERAL COMMENT BY berkey: Thu Dec 31 03:09:27 GMT 2020

Ucomp alignment this morning showed some confusing results. Looks like we might not have had the bessel beam alignment we expected.

Current plan is the use what we learned over these pervious alignments to; pull the optics and start the alignment from sc ratch confirming everything as we go.

____end___

ONSITE STAFF: berkey