```
Mauna Loa Solar Observatory Observer's Log
      Thu Jul 21 17:08:51 GMT 2022
Year: 22 Doy: 202
Observer: berkey
WEATHER COMMENT: berkey: Thu Jul 21 17:08:37 GMT 2022
Temp: 46.2f, Humidity: 12%, Pressure: 28.683in, Wind: 1mph from 203degs, Skies: clear
GENERAL COMMENT BY berkey: Thu Jul 21 17:08:40 GMT 2022
PM Blew off Kcor O1
 __end__
GENERAL COMMENT BY berkey: Thu Jul 21 17:08:44 GMT 2022
PM Blew off UCoMP 01
GENERAL COMMENT BY berkey: Thu Jul 21 17:10:02 GMT 2022
Static line (grounding line) between power pole 177 and 178 (around 11 miles up the roa
d) blew down last night. Power to the site remained on but I suspect when crews come o
n site to fix this line they will bring power down to safely access the poles.
  end
Thu Jul 21 17:11:11 GMT 2022 Kcor Focus/alignment program exited
Thu Jul 21 17:23:44 GMT 2022 Running UCOMP Cookbook all_wavelength_coronal.cbk line 0
Thu Jul 21 17:57:37 GMT 2022 Running UCOMP Cookbook all_wavelength_coronal.cbk line 0
Thu Jul 21 18:31:20 GMT 2022 Running UCOMP Cookbook all_wavelength_coronal.cbk line 0
Thu Jul 21 19:04:53 GMT 2022 Running UCOMP Cookbook all_wavelength_coronal_flat.cbk lin
Thu Jul 21 19:23:14 GMT 2022 Running UCOMP Cookbook waves_1074_1hour.cbk line 0
****EVENT COMMENT BY berkey**** : Thu Jul 21 19:47:00 GMT 2022
Bright prominence eruption at PA 260 seen in kcor, launching around 17UT. Kcor pipelin
e tags this a cme; but at least at this poinnt it doesn't look like material is leaving
 the sun.
  end
Thu Jul 21 20:33:03 GMT 2022 Running UCOMP Cookbook dark_80ms_2beam_16sums_BOTH.cbk lin
Thu Jul 21 20:34:20 GMT 2022 Running UCOMP Cookbook 637_Pol_Calibrate.cbk line 0
Thu Jul 21 20:38:24 GMT 2022 Running UCOMP Cookbook 706_Pol_Calibrate.cbk line 0
Thu Jul 21 20:42:27 GMT 2022 Running UCOMP Cookbook 789_Pol_Calibrate.cbk line 0
Thu Jul 21 20:43:15 GMT 2022 UCoMP Paused for clouds
GENERAL COMMENT BY berkey: Thu Jul 21 20:51:53 GMT 2022
Low clouds plaguing the area for the next little bit.
  _end_
GENERAL COMMENT BY berkey: Thu Jul 21 21:23:19 GMT 2022
Dome wsa closed about 10 minutes ago.
  end
GENERAL COMMENT BY berkey: Thu Jul 21 23:05:23 GMT 2022
Attempted to configure new network equipment hit a hiccup. System is currently running
in its nominal condition. Work will resume early next week.
GENERAL COMMENT BY berkey: Fri Jul 22 00:31:45 GMT 2022
Power outage.
  end
Fri Jul 22 01:02:11 GMT 2022 UCoMP Restarted from pause
UCOMP COMMENT BY berkey: Fri Jul 22 01:12:37 GMT 2022
```

Initial checks showed 12V at the fan. So a replacement was pulled from the old PSPT equipment and installed. This fan also showed slower than expected rotation.

Found the UCoMP camera cooling radiator fan was spinning slower than expected.

On further inspection the negative lead on the facility side of the screw down termal n ext to the fan was a little loose. Tightened this termail restored what looked like no rmal rotation. However it still doesnt feel like very much flow across the radiator.

```
Original fan is now in the ucomp spares box in the cabinet.
__end___
GENERAL COMMENT BY berkey: Fri Jul 22 02:12:46 GMT 2022
Power is back.
```

end GENERAL COMMEN	Г ВҮ	berkey:	Fri	Jul	22	02:33:38	GMT	2022
<pre>end ONSITE STAFF:</pre>	berk	ey						