University of Tennessee Knoxville

Job Hazard Analysis and Personal Protective Equipment Assessment

Instructions for Supervisors: Please review all applicable Job Hazard Analysis forms with your employee. The forms are categorized by job task.

Hazard Analysis:

Drill Bit Sharpener

Task	Hazard	Cause	Prevention
General Use	Eye Injury	Projectiles, filings	Safety glasses with side shield or appropriate safety goggles
	Hand Injury	Point of operation, ingoing nip points, rotating parts, flying chips and sparks	Situational awareness
	Electrical Shock	Improper grounding, improper operations and maintenance	Proper grounding of frame, manufacturer's instructions strictly followed

PPE Required:

• Safety Glasses w/side shield

This document serves as the Personal Protective Equipment (PPE) Certification document required to satisfy the federal requirements of the Occupational Safety and Health Administration (OSHA) Standard, 29 CFR 1910.132 Subpart I- Personal Protective Equipment. This certifies that a hazard assessment of workplace hazards has been performed. Signatures for the certification are on file in the Environmental Health and Safety Department office. For questions and more information about this document, please contact EHS at 974-5084 or safety @utk.edu.

<u>April W. Case</u> EHS Team Leader General Safety