

## University of Tennessee Knoxville

### Job Hazard Analysis and Personal Protective Equipment Assessment

Instructions for Supervisors: Please review all applicable Job Hazard Analysis forms with your employee. The forms are categorized by job task.

Hazard Analysis:

#### Forklift

Task	Hazard	Cause	Prevention
General Use	Trauma	Projectiles, impact, vibration, burns	Situational awareness, gloves, switch guards
	Foot Injury	Dropped object on foot	Wear safety shoes
	Noise	Engine, impact	Wear hearing protection
	Eye	Fluid splash when servicing	Wear safety goggles
	Eye	Battery charging station	Wear safety goggles, ensure there is a drenching station (eyewash)

**Ensure only trained and authorized users operate Power Industrial Trucks (forklifts).**

#### PPE Required:

- Safety goggles
- Safety Shoes/boots
- Hearing Protection
- Gloves

This document serves as the Personal Protective Equipment (PPE) Certification document required to satisfy the federal requirements of the Occupational Safety and Health Administration (OSHA) Standard, 29 CFR 1910.132 Subpart I- Personal Protective Equipment. This certifies that a hazard assessment of workplace hazards has been performed. Signatures for the certification are on file in the Environmental Health and Safety Department office. For questions and more information about this document, please contact EHS at 974-5084 or safety @utk.edu.

*April W. Case*

EHS Team Leader General Safety

Date 12/4/2017