

**University of Tennessee Knoxville**
**Job Hazard Analysis and Personal Protective Equipment Assessment**

Instructions for Supervisors: Please review all applicable Job Hazard Analysis forms with your employee. The forms are categorized by job task.

Hazard Analysis:

**Fuel Transfer Pump**

<b>Task</b>	<b>Hazard</b>	<b>Cause</b>	<b>Prevention</b>
General Use	Eye Injury	Fuel splashes	Goggles
	Hand Injury	Fuel contact in sub-zero weather	Gloves
	Fire, Explosion	Smoking, sparks, improper grounding and bonding	No smoking or exposure to sparks or open flame during fueling. Fill stem shall be bonded to the container during filling operations by means of a bond wire. Appropriate placed fire extinguisher.

PPE Required:

- Goggles
- Gloves

This document serves as the Personal Protective Equipment (PPE) Certification document required to satisfy the federal requirements of the Occupational Safety and Health Administration (OSHA) Standard, 29 CFR 1910.132 Subpart I- Personal Protective Equipment. This certifies that a hazard assessment of workplace hazards has been performed. Signatures for the certification are on file in the Environmental Health and Safety Department office. For questions and more information about this document, please contact EHS at 974-5084 or safety @utk.edu.

*April W. Case*

EHS Team Leader General Safety

Date 12/4/2017