

University of Tennessee Knoxville**Job Hazard Analysis and Personal Protective Equipment Assessment**

Instructions for Supervisors: Please review all applicable Job Hazard Analysis forms with your employee. The forms are categorized by job task.

Hazard Analysis:Pressurized Cooling System Tester

Task	Hazard	Cause	Prevention
General Use	Eye Injury, Skin irritation	Coolant splashes	Goggles, face shield, apron, gloves, proper operation of coolant tester

PPE Required:

- Apron
- Gloves
- Goggles
- Face Shield

This document serves as the Personal Protective Equipment (PPE) Certification document required to satisfy the federal requirements of the Occupational Safety and Health Administration (OSHA) Standard, 29 CFR 1910.132 Subpart I- Personal Protective Equipment. This certifies that a hazard assessment of workplace hazards has been performed. Signatures for the certification are on file in the Environmental Health and Safety Department office. For questions and more information about this document, please contact EHS at 974-5084 or safety@utk.edu.

April W. Case

EHS Team Leader General Safety

Date 12/4/2017