

University of Tennessee Knoxville
Job Hazard Analysis and Personal Protective Equipment Assessment

Instructions for Supervisors: Please review all applicable Job Hazard Analysis forms with your employee. The forms are categorized by job task.

Hazard Analysis:

Vehicle Lift

Task	Hazard	Cause	Prevention
General Use	Foot Injury	Drop object on foot	Wear safety shoes
	Trauma	Overloading lift beyond rated capacity. Operator error. Not following manufacturer's instruction or safety warnings	Never exceed loading capacity. Ensure that rated load is legibly and permanently marked in a prominent location. Ensure each operator has received adequate training on operation of lift. Follow manufacturer's instructions and warnings.
	Eye Injury	Debris	Safety glasses with side shield/goggles
	Eye Injury	Fluids	Goggles

PPE Required:

- Safety Shoes/Boots
- Safety glasses with side shield
- Goggles

This document serves as the Personal Protective Equipment (PPE) Certification document required to satisfy the federal requirements of the Occupational Safety and Health Administration (OSHA) Standard, 29 CFR 1910.132 Subpart I- Personal Protective Equipment. This certifies that a hazard assessment of workplace hazards has been performed. Signatures for the certification are on file in the Environmental Health and Safety Department office. For questions and more information about this document, please contact EHS at 974-5084 or safety @utk.edu.

April W. Case

EHS Team Leader General Safety

Date 12/4/2017