University of Tennessee Knoxville

Job Hazard Analysis and Personal Protective Equipment Assessment

Instructions for Supervisors: Please review all applicable Job Hazard Analysis forms with your employee. The forms are categorized by job task.

Hazard Analysis:

Pallet Jack & Dolly, Hydraulic

Task	Hazard	Cause	Prevention
General Use	Foot Injury	Roll jack over foot	Wear safety shoes
	Trauma	Overloading jack beyond rated capacity, using jack for support rather than just lifting, sharp objects	Follow manufacturer's instructions, gloves

PPE Required:

- Safety Shoes/Boots
- Gloves

This document serves as the Personal Protective Equipment (PPE) Certification document required to satisfy the federal requirements of the Occupational Safety and Health Administration (OSHA) Standard, 29 CFR 1910.132 Subpart I- Personal Protective Equipment. This certifies that a hazard assessment of workplace hazards has been performed. Signatures for the certification are on file in the Environmental Health and Safety Department office. For questions and more information about this document, please contact EHS at 974-5084 or safety @utk.edu.

<u>April W. Case</u> EHS Team Leader General Safety