

6312 NW 18<sup>th</sup> Drive  
Suite 100  
Gainesville, FL 32653

352.378.0332 PHONE  
352.378.0354 FAX

[www.TRCSolutions.com](http://www.TRCSolutions.com)

January 13, 2015

Ms. Lori Simmons  
Arkansas Department of Health  
4815 West Markham Street  
Little Rock, Arkansas 72205  
Via email [Lori.Simmons@arkansas.gov](mailto:Lori.Simmons@arkansas.gov)

**Re: Georgia-Pacific, Crossett mill - Biweekly Air Monitoring Report for Hydrogen Sulfide  
– Revised**

Dear Ms. Simmons,

Following is a data summary for the sixth two-week operational period of the Georgia-Pacific (GP) hydrogen sulfide (H<sub>2</sub>S) and meteorological monitoring program at the GP Crossett mill.

#### Summary of Results

Included in this report are three plots presenting H<sub>2</sub>S concentrations calculated with varied rolling average periods (30-minute, 8-hour, and 24-hour). Also included in this report is a summary of results from the daily 1-point QC checks performed during this biweekly period. The QAPP establishes goals for precision and bias as a coefficient of variation (CV) <10% and ± 10%, respectively. Precision and bias are calculated in accordance with 40 CFR Part 58 Appendix A, Section 4.1.

Fourteen-day time series plots for all recorded meteorological (met) parameters are presented in the final table. All met parameters have 100% data capture for this report period.

There was one occurrence of data loss during this two week period, in addition to those resulting from automated daily 1-point QC and weekly calibration checks. During a site visit on December 16<sup>th</sup>, TRC replaced the disk on module (DOM) that stores the instrument's configuration and reloaded the firmware. Following replacement of the DOM, a complete calibration was performed.

Please note, the 1-point QC check was not performed during the regularly scheduled time due to the DOM replacement. A single check point from the calibration performed following the DOM replacement was used to replace the missing 1-point QC check on the 16<sup>th</sup> in the CV calculation for this biweekly period.

Results for all automated daily 1-point QC checks fall within the acceptable range, indicating the H<sub>2</sub>S monitor was operating in accordance with the QAPP.



Jan 13, 2015

Please feel free to contact me if you have any questions or need any additional data.

Sincerely,




---

Jonathan Bowser  
Manager, Air Quality and Meteorological Monitoring


Air Measurements – Gainesville Office  
6312 NW 18th Drive, Suite 100  
Gainesville, Florida 32653  
(352) 260-1162  
Email: [jbowser@trcsolutions.com](mailto:jbowser@trcsolutions.com)

CC: Ryan Benefield, ADEQ Director via email: [benefield@adeq.state.ar.us](mailto:benefield@adeq.state.ar.us)  
Kara Allen, Environmental Engineer, USEPA Region 6 via email [Allen.Kara@epa.gov](mailto:Allen.Kara@epa.gov)


### H<sub>2</sub>S 30 Min Rolling Avg Georgia Pacific Crossett, AR



## H<sub>2</sub>S 8 Hr Rolling Avg Georgia Pacific Crossett, AR



## H<sub>2</sub>S 24 Hr Rolling Avg Georgia Pacific Crossett, AR



Meteorological Summary

