

| Lynn Harbor, Massachusetts | | | | | Date 08/16/2021 |
|--|-------|----------------------|-------------|-----------------------|---------------------------|
| Sheet Name | Depth | Left Outside Quarter | Middle Half | Right Outside Quarter | Survey Name |
| Lynn Harbor 22-Foot Broad Sound Reach | 22 | +1.0 | 13.8 | 12.8 | MA_12_LYN_20210706_CS_030 |
| Lynn Harbor 22-Foot Little Nahant Reach | 22 | 7.2 | 16.1 | 9.7 | MA_12_LYN_20210706_CS_030 |
| Lynn Harbor 22-Foot Sandy Point Reach | 22 | 11.2 | 16.0 | +0.9 | MA_12_LYN_20210706_CS_030 |
| Lynn Harbor 22-Foot Turning Basin | 22 | 5.6 | | | MA_12_LYN_20210706_CS_030 |

| |
|------------------------------------|
| 7 or more feet above project depth |
| 5 or 6 feet above project depth |
| 3 or 4 feet above project depth |
| 1 or 2 feet above project depth |
| At or 1 foot below project depth |
| 2 or 3 feet below project depth |
| 4 feet or more below project depth |