

## Southeast Corridor Track Repair 48 Hour Update

### SE Corridor Track Repair Update

<b>Date:</b>	6.28.2024	<b>Reported by:</b>	Brian Farris
<b>Time (military):</b>	1430	<b>Job Title:</b>	General Superintendent, Infrastructure MOW

**Work completed in the last 48 hours:**

This report covers Thursday 6/27/24 and Friday 6/28/24.

In the last 48 hours the Maintenance of Way (MOW) department has successfully installed one, 39' stick of rail and shortened the length of the speed restriction on the outbound track in segment #52 to 10MPH for a 1500' section from Orchard Station to Arapahoe Station. Five 39' sticks of rail and two insulated joint plugs were hauled to Orchard for staging of future rail replacements. Rail head defects were ground in the same area as well. These rail defects were worked during the 11:00 p.m. to 5:00 a.m. work window. Rail replacement will continue on 6/30/24-7/1/2024 in segment #52, Orchard to Arapahoe.

Joint bars installation and rail grinding were performed in the work window in segment #53, Arapahoe to Dry Creek and the speed restriction on the inbound track has been reduced to a 1500' section.