

-----  
Mauna Loa Solar Observatory Observer's Log  
-----

Wed Sep 16 17:12:48 GMT 1998

Year: 98 Doy: 259

Observer: koon

WEATHER COMMENT: Wed Sep 16 17:12:56 GMT 1998

Clear sky, wind=5 mph from the SE, temp=50 F.

Wed Sep 16 17:14:09 GMT 1998 CHIP Startup--Initializing new tape

Wed Sep 16 17:22:17 GMT 1998 MKIII Start Patrol

Wed Sep 16 17:22:43 GMT 1998 PICS Start Patrol

Wed Sep 16 17:45:46 GMT 1998 MKIII End Patrol

Wed Sep 16 17:47:18 GMT 1998

MKIII COMMENT: Wed Sep 16 17:49:31 GMT 1998

When I started this morning I typed Run in the xterm window instead of the cmdtool window. This caused some problems, the animations display didn't work, the data scan files are named incorrectly. I exited and cycled the main power switch and restarted everything for the MKIII. That fixed the problems. I will delete the misnamed files, there are only 20 minutes worth.

Wed Sep 16 18:01:53 GMT 1998 CHIP Bias

Wed Sep 16 18:02:41 GMT 1998 PICS Flat

Wed Sep 16 18:02:55 GMT 1998 CHIP End Bias

Wed Sep 16 18:03:09 GMT 1998 CHIP Water

Wed Sep 16 18:03:50 GMT 1998 CHIP End Water

Wed Sep 16 18:04:12 GMT 1998 PICS End Flat

Wed Sep 16 19:02:00 GMT 1998 CHIP Bias

Wed Sep 16 19:02:39 GMT 1998 PICS Flat

Wed Sep 16 19:03:06 GMT 1998 CHIP End Bias

Wed Sep 16 19:03:16 GMT 1998 CHIP Water

Wed Sep 16 19:04:00 GMT 1998 CHIP End Water

Wed Sep 16 19:04:00 GMT 1998 CHIP End Water

\*\*PSPT PROBLEM\*\* Wed Sep 16 19:52:53 GMT 1998

Mirror is oscillating again, the sky is clear.

I exited the program while the mirror drive was off, so it can cool down.

Wed Sep 16 20:01:55 GMT 1998 CHIP Gain

Wed Sep 16 20:02:44 GMT 1998 PICS Flat

Wed Sep 16 20:04:12 GMT 1998 PICS End Flat

Wed Sep 16 20:06:33 GMT 1998 CHIP End Gain

Wed Sep 16 20:06:48 GMT 1998 CHIP Bias

Wed Sep 16 20:07:38 GMT 1998 CHIP End Bias

Wed Sep 16 20:07:48 GMT 1998 CHIP Water

Wed Sep 16 20:08:24 GMT 1998 CHIP End Water

\*\*PSPT PROBLEM\*\* Wed Sep 16 20:12:21 GMT 1998

There doesn't appear to be any fans in the electronics rack to cool the mirror drive board. I pulled it out and am letting it cool down before I observe.

\*\*PSPT PROBLEM\*\* Wed Sep 16 20:30:44 GMT 1998

I installed the driver board and used Run to start observing.

COMMENT: Wed Sep 16 20:39:04 GMT 1998

Extended the dome slot.

Wed Sep 16 21:02:41 GMT 1998 PICS Flat  
Wed Sep 16 21:02:49 GMT 1998 CHIP Bias  
Wed Sep 16 21:03:47 GMT 1998 CHIP End Bias  
Wed Sep 16 21:03:57 GMT 1998 CHIP Water  
Wed Sep 16 21:04:08 GMT 1998 PICS End Flat  
Wed Sep 16 21:04:43 GMT 1998 CHIP End Water

COMMENT: Wed Sep 16 21:19:52 GMT 1998

Lost guiding in declination, repointed.

Wed Sep 16 22:02:46 GMT 1998 PICS Flat  
Wed Sep 16 22:03:14 GMT 1998 CHIP Bias  
Wed Sep 16 22:04:16 GMT 1998 PICS End Flat  
Wed Sep 16 22:04:21 GMT 1998 CHIP End Bias  
Wed Sep 16 22:04:31 GMT 1998 CHIP Water  
Wed Sep 16 22:05:12 GMT 1998 CHIP End Water

\*\*PSPT PROBLEM\*\* Wed Sep 16 22:11:01 GMT 1998

I found the fans for the electronics rack, they are at the bottom of the rack, there are 3 of them and they blow air up through the electronics. They are

still functioning but how well they cool is dubious since the rack is only vented at the top with no cool air inlets down low. But the mirror drive module didn't get very hot so maybe it only gets hot after something causes the mirror oscillation to take place. Haosheng is sending out a spare mirror driver board for us to try. By the way, pull out a few of the bigger modules in the lowest section of the cabinet to be able to see the fans from the front of the cabinet.

Wed Sep 16 22:26:06 GMT 1998 CHIP ending tape

COMMENT: Wed Sep 16 22:40:03 GMT 1998

Tapes:

\*\*\*\*\*

PICS: P01295

CHIP: C00692

LOWL: L00543 in drive #1

Wed Sep 16 22:40:57 GMT 1998

MkIII

|              |              |              |              |              |
|--------------|--------------|--------------|--------------|--------------|
| 17_50.rawmk3 | 18_43.rawmk3 | 19_45.rawmk3 | 20_38.rawmk3 | 21_30.rawmk3 |
| 17_53.rawmk3 | 18_46.rawmk3 | 19_48.rawmk3 | 20_41.rawmk3 | 21_33.rawmk3 |
| 17_56.rawmk3 | 18_49.rawmk3 | 19_51.rawmk3 | 20_43.rawmk3 | 21_36.rawmk3 |
| 17_59.rawmk3 | 18_51.rawmk3 | 19_54.rawmk3 | 20_46.rawmk3 | 21_39.rawmk3 |
| 18_02.rawmk3 | 18_54.rawmk3 | 19_57.rawmk3 | 20_49.rawmk3 | 21_42.rawmk3 |
| 18_05.rawmk3 | 18_57.rawmk3 | 20_00.rawmk3 | 20_52.rawmk3 | 21_45.rawmk3 |
| 18_08.rawmk3 | 19_00.rawmk3 | 20_03.rawmk3 | 20_55.rawmk3 | 21_48.rawmk3 |
| 18_11.rawmk3 | 19_03.rawmk3 | 20_05.rawmk3 | 20_58.rawmk3 | 21_51.rawmk3 |
| 18_13.rawmk3 | 19_06.rawmk3 | 20_08.rawmk3 | 21_01.rawmk3 | 21_54.rawmk3 |

|              |              |              |              |               |
|--------------|--------------|--------------|--------------|---------------|
| 18_16.rawmk3 | 19_09.rawmk3 | 20_11.rawmk3 | 21_04.rawmk3 | 21_57.rawmk3  |
| 18_19.rawmk3 | 19_15.rawmk3 | 20_14.rawmk3 | 21_07.rawmk3 | 21_59.rawmk3  |
| 18_22.rawmk3 | 19_21.rawmk3 | 20_17.rawmk3 | 21_10.rawmk3 | 22_02.rawmk3  |
| 18_25.rawmk3 | 19_27.rawmk3 | 20_20.rawmk3 | 21_13.rawmk3 | 22_05.rawmk3  |
| 18_28.rawmk3 | 19_30.rawmk3 | 20_23.rawmk3 | 21_16.rawmk3 | 22_08.rawmk3  |
| 18_31.rawmk3 | 19_33.rawmk3 | 20_26.rawmk3 | 21_19.rawmk3 | 22_11.rawmk3  |
| 18_34.rawmk3 | 19_36.rawmk3 | 20_29.rawmk3 | 21_21.rawmk3 | c19_12.rawmk3 |
| 18_37.rawmk3 | 19_39.rawmk3 | 20_32.rawmk3 | 21_24.rawmk3 | c19_18.rawmk3 |
| 18_40.rawmk3 | 19_42.rawmk3 | 20_35.rawmk3 | 21_27.rawmk3 | c19_24.rawmk3 |