```
Mauna Loa Solar Observatory Observer's Log
______
      Sat Jan 17 17:28:55 GMT 2015
Year: 15 Doy: 017
Observer: stueben
WEATHER COMMENT: stueben: Sat Jan 17 17:29:03 GMT 2015
Clear, wind south 5 mph, temp 38F.
end
Sat Jan 17 17:46:56 GMT 2015 COMP Start Patrol
Sat Jan 17 18:07:50 GMT 2015 KCOR Start Synoptic Patrol
Sat Jan 17 19:01:52 GMT 2015 KCOR End Patrol
Sat Jan 17 19:01:53 GMT 2015 KCOR Start Calibration script: c:\kcor\mlso-calibration22deq.ini
Sat Jan 17 19:17:23 GMT 2015 KCOR End Calibration Script
Sat Jan 17 19:17:40 GMT 2015 KCOR Start Synoptic Patrol
Sat Jan 17 19:17:41 GMT 2015 KCOR Start Synoptic Patrol
Sat Jan 17 20:44:26 GMT 2015 COMP End Patrol
Sat Jan 17 20:47:47 GMT 2015 COMP Start Patrol
GENERAL OBSERVATORY COMMENT BY stueben: Sat Jan 17 20:48:21 GMT 2015
Adjusted sqs offsets.
end
Sat Jan 17 23:45:26 GMT 2015 COMP End Patrol
Sat Jan 17 23:48:04 GMT 2015 COMP Start Patrol
**PSPT PROBLEM COMMENT BY stueben** : Sun Jan 18 02:12:41 GMT 2015
The replacement dome motor capacitor arrived. Rewired the motor, cable, and
motor controller box. Remounted the motor on the dome. Motor moves OK in both
directions using the manual control. Reversed the motor direction windings so
that the position change increases in the clockwise direction as the pc expects.
PC refuses to move dome, an error message indicates that the home switch is
activated (which mechanically it is not). Ran out of time/energy to pursue the
home switch problem, perhaps the cable/connector/switch was damaged in taking
off and putting on the motor twice.
end
```

Sun Jan 18 02:38:56 GMT 2015 COMP End Patrol Sun Jan 18 02:39:21 GMT 2015 KCOR End Patrol