```
Mauna Loa Solar Observatory Observer's Log
 ______
      Fri Feb 10 17:11:42 GMT 2017
Year: 17 Doy: 041
Observer: berkey
WEATHER COMMENT: berkey: Fri Feb 10 17:12:04 GMT 2017
Temp: 44.2f, Humidity: 7%, Pressure: 28.636in, Wind: 15mph from 265degs, Skies: Mostly clear with bands of cirrus toward z
enith and the west.
end
Fri Feb 10 17:42:07 GMT 2017 CoMP occulter has been re-centered
Fri Feb 10 17:43:45 GMT 2017 COMP Start Patrol on cookbook: synoptic-00010.cbk
Fri Feb 10 17:48:11 GMT 2017 Kcor Focus/alignment program exited
GENERAL COMMENT BY berkey: Fri Feb 10 17:58:06 GMT 2017
Running of some cirrus as soon as kcor got up and running. : (
 end
Fri Feb 10 17:59:22 GMT 2017 CoMP Paused for clouds
Fri Feb 10 18:17:59 GMT 2017 CoMP Restarted from pause
Fri Feb 10 18:32:29 GMT 2017 CoMP Paused for clouds
Fri Feb 10 18:56:07 GMT 2017 CoMP Restarted from pause
Fri Feb 10 19:04:20 GMT 2017 KCOR Start Synoptic Patrol
Fri Feb 10 19:13:35 GMT 2017 KCOR End Patrol
Fri Feb 10 19:13:49 GMT 2017 CoMP Paused for clouds
Fri Feb 10 19:18:30 GMT 2017 CoMP Restarted from pause
Fri Feb 10 19:19:25 GMT 2017 KCOR Start Synoptic Patrol
Fri Feb 10 19:24:34 GMT 2017 KCOR End Patrol
Fri Feb 10 19:24:35 GMT 2017 KCOR Start Calibration script: c:\kcor\mlso-calibration22deg-20150323.ini
Fri Feb 10 19:41:38 GMT 2017 KCOR End Calibration Script
Fri Feb 10 19:41:55 GMT 2017 KCOR Start Synoptic Patrol
Fri Feb 10 19:41:56 GMT 2017 KCOR Start Synoptic Patrol
Fri Feb 10 19:45:52 GMT 2017 KCOR End Patrol
Fri Feb 10 19:48:51 GMT 2017 CoMP Paused for clouds
KCOR COMMENT BY berkey: Fri Feb 10 19:50:30 GMT 2017
Kcor was showing incorrect cal-pol positions. For some reason valuges bigger then 360 showed up includeing 691. I think
this was related to the homing processes and all data/calibration files have the correct calpol but it was odd to see a va
lue outside the range 0-360.
  end
Fri Feb 10 20:33:31 GMT 2017 CoMP Restarted from pause
Fri Feb 10 20:49:40 GMT 2017 CoMP Paused for clouds
Sat Feb 11 01:03:04 GMT 2017 CoMP Restarted from pause
Sat Feb 11 01:03:04 GMT 2017 COMP End Patrol
GENERAL COMMENT BY berkey: Sat Feb 11 01:05:03 GMT 2017
Moved the building camera over from its origional enclosure to a a cctv style enclousre that another project up here was s
urplusing.
```

During the process sd card that runs the camera got corrupted so a bit of time as spend trying to re-remember how to setup the system.

Also during the process the window got a bit of a goober on it. I have tried to clean it with some wind but seme to be mo stly smeering things around. So at this point I think I will stop and just see if it will get better while drying out over the weekend.

Hopefully this new encolsure with its glass window will get rid of the annoying reflections/streaks that followed the sun in the winter months.

__end___
GONG COMMENT BY berkey: Sat Feb 11 02:45:36 GMT 2017

GONG COMMENT BY berkey: Sat Feb 11 02:45:36 GMT 2017

Swapped a hard drive in the gong halpah machine per a request form Tim.

__end___

GENERAL OBSERVATORY COMMENT BY berkey: Sat Feb 11 02:46:01 GMT 2017

Very very dry day up here %5 humidty is hard on my eyes.

end