

-----  
Mauna Loa Solar Observatory Observer's Log  
-----

Wed Mar 6 17:58:27 GMT 2019

Year: 19 Doy: 065

Observer: berkey

WEATHER COMMENT: berkey: Wed Mar 06 18:01:55 GMT 2019

Temp: 40.2f, Humidity: 25%, Pressure: 28.673in, Wind: 3mph from 169degs, Skies: heavy overcast

\_\_\_\_end\_\_\_\_

KCOR COMMENT BY berkey: Wed Mar 06 18:02:38 GMT 2019

Testing changes the kcor header obsswid keyword

\_\_\_\_end\_\_\_\_

GENERAL COMMENT BY berkey: Wed Mar 06 18:02:39 GMT 2019

\_\_\_\_end\_\_\_\_

Wed Mar 06 18:03:46 GMT 2019 Kcor Focus/alignment program exited

Wed Mar 06 21:34:37 GMT 2019 Kcor Focus/alignment program exited

KCOR COMMENT BY berkey: Wed Mar 06 22:01:15 GMT 2019

Bad T-cam removed from Kcor

New t-cam 13889 installed and focused.

Kcor observing code updated to support 2 cameras again and the kcorconfig.ini file has be updated to point to 13889.

With a quick test on a overcast sky; all systems seem to be go.

\_\_\_\_end\_\_\_\_

GENERAL COMMENT BY berkey: Thu Mar 07 01:16:47 GMT 2019

Replaced 3 of the kcor hepa vibration isolation pads becasue the rubbber was close to failure.

\_\_\_\_end\_\_\_\_

ONSITE STAFF: berkey