

University of Tennessee Knoxville
Job Hazard Analysis and Personal Protective Equipment Assessment

Instructions for Supervisors: Please review all applicable Job Hazard Analysis forms with your employee. The forms are categorized by job task.

Hazard Analysis:

Dust Collector, Vacuum

Task	Hazard	Cause	Prevention
General Use	Foot Injury	Drop object on foot	Wear safety shoes
	Electric Shock	Improper operation and maintenance, improper grounding	Manufacturer's instructions strictly followed, proper grounding
	Eye Injury	Flying Debris	Wear safety glasses w/side shields
	Noise	Equipment Operation	Use hearing protection

PPE Required:

- Safety Glasses with side shield
- Hearing Protection
- Safety Shoes/Boots

This document serves as the Personal Protective Equipment (PPE) Certification document required to satisfy the federal requirements of the Occupational Safety and Health Administration (OSHA) Standard, 29 CFR 1910.132 Subpart I- Personal Protective Equipment. This certifies that a hazard assessment of workplace hazards has been performed. Signatures for the certification are on file in the Environmental Health and Safety Department office. For questions and more information about this document, please contact EHS at 974-5084 or safety @utk.edu.

April W. Case

EHS Team Leader General Safety

Date 12/4/2017