

University of Tennessee Knoxville
Job Hazard Analysis and Personal Protective Equipment Assessment

Instructions for Supervisors: Please review all applicable Job Hazard Analysis forms with your employee. The forms are categorized by job task.

Hazard Analysis:

Framing Nail Gun, Impact

Task	Hazard	Cause	Prevention
General Use	Inhalation	Exhausts	Use only in well ventilated areas
	Eye Injury	Projectiles	Safety glasses with side shield or appropriate safety goggles
	Noise	Machine operation	Hearing protection
	Foot Injury	Drop object on foot	Wear safety shoes
	Hand Injury	Point of operation	Situational awareness
	Fire	Hot exhaust gases	Appropriate placed fire extinguisher, remove all combustibles and fire hazards

PPE Required:

- Safety Glasses with side shields/Safety Goggles
- Hearing Protection
- Safety Shoes/Boots

This document serves as the Personal Protective Equipment (PPE) Certification document required to satisfy the federal requirements of the Occupational Safety and Health Administration (OSHA) Standard, 29 CFR 1910.132 Subpart I- Personal Protective Equipment. This certifies that a hazard assessment of workplace hazards has been performed. Signatures for the certification are on file in the Environmental Health and Safety Department office. For questions and more information about this document, please contact EHS at 974-5084 or safety @utk.edu.

April W. Case

EHS Team Leader General Safety

Date 12/4/2017