

University of Tennessee Knoxville
Job Hazard Analysis and Personal Protective Equipment Assessment

Instructions for Supervisors: Please review all applicable Job Hazard Analysis forms with your employee. The forms are categorized by job task.

Hazard Analysis:

Portable Generator, Gasoline Powered

Task	Hazard	Cause	Prevention
General Use	Inhalation	Exhaust	Appropriate ventilation
	Trauma	Burns	Situational awareness, PPE, protective clothing
	Foot Injury	Roll over foot, drop object on foot	Wear safety shoes
	Fire	Heat, sparks, slag	Appropriate placed fire extinguisher, remove all combustibles and fire hazards from area
	Electrical Shock	Improper operations and maintenance, improper switching device	Strictly follow manufacturer's instructions, proper switching for starting up/ shutting down machine

Never use a generator indoors. Always use in a well ventilated area.

PPE Required:

- Leather Gloves
- Safety Shoes/ Boots

This document serves as the Personal Protective Equipment (PPE) Certification document required to satisfy the federal requirements of the Occupational Safety and Health Administration (OSHA) Standard, 29 CFR 1910.132 Subpart I- Personal Protective Equipment. This certifies that a hazard assessment of workplace hazards has been performed. Signatures for the certification are on file in the Environmental Health and Safety Department office. For questions and more information about this document, please contact EHS at 974-5084 or safety @utk.edu.

April W. Case

EHS Team Leader General Safety

Date 12/4/2017