

**Tropical Storm Joshephine (Edgewater Tornado)
10/7/96**

[NWS Southern Region's Service Enhancement Project \(PDF\)](#)
(event summary)

Damage Photos:



Crossing I-95 mile marker 241 (east side)



Tree Damage on Airpark Road



Hole knocked through block garage wall, Airpark Road



Tree damage to home



Tree down on car



Severe Roof Damage