



# 129,000 Pound Evaluation of US-89

## M.P. 41.17 to M.P 44.24

(Case #201618US89)

### Executive Summary

Handy Truck Line submitted a request for 129,000 pound trucking approval on US-89 between mile post (MP) 41.17 and MP 44.24 for transportation of cement. The request projects up to 20-60 trips annually which is a 15-20% reduction from current operations. The requested section of US-89 is designated as a red route and as such all trucks must adhere to the 6.5-foot off-track and 115-foot overall vehicle length criteria. ITD Bridge Section confirms the two bridges on the route will safely support 129,000 pound vehicles. District analysis shows this section of road as a rural principal arterial in fair to good condition with no deficient sections. The Department's Materials Section evaluation shows that increased vehicle weight with a corresponding increased number of axles will reduce loads per axle compared to 80,000 or 105,500 pound vehicles and thereby produce lower loads on the road surface and subsurface resulting in equal or lesser damage. The Office of Highway Safety analysis shows this section of US-89 has no Non-Interstate High Accident Intersection Locations (HAL) and has no HAL Clusters. Department of Motor Vehicles, Materials Section, Highway Safety, Bridge Asset Management and District 5 all recommend proceeding with this request.

### Detailed Analysis

#### **Department of Motor Vehicles (DMV) Review**

All Idaho Transportation Department routes are currently categorized by their ability to handle various extra-length vehicle combinations and their off-tracking allowances. The categories used when considering allowing vehicle combinations to carry increased axle weights above 105,500 pounds and up to 129,000 pounds are:

- Blue routes at 95 foot overall vehicle length and a 5.50-foot off-track
- Red routes at 115 foot overall vehicle length and a 6.50-foot off-track.

Off-tracking is the turning radius of the vehicle combination, which assists in keeping them safely in their lane of travel. Off-tracking occurs because the rear wheels of trailer trucks do not pivot, and therefore will not follow the same path as the front wheels. The greater the distance between the front wheels and the rear wheels of the vehicle, the greater the amount of off-track. The DMV confirms that the requested routes falls under one of the above categories and meets all length and off-tracking requirements for that route. **More specifically, the requested section of US-89 from milepost 41.17 to 44.24 is designated as a red route and as such all trucks must adhere to the 6.5-foot off-track and 115-foot overall vehicle length criteria.**

## Bridge Review

Bridges on all publicly owned routes in Idaho, with the exception of those meeting specific criteria, are inspected every two years at a minimum to ensure they can safely accommodate vehicles. A variety of inspections may be performed including routine inspections, in-depth inspections, underwater inspections, and complex bridge inspections. All are done to track the current condition of a bridge and make repairs if needed.

When determining the truck-carrying capacity of a bridge, consideration is given to the types of vehicles that routinely use the bridge and the condition of the bridge. Load limits may be placed on a bridge if, through engineering analysis, it is determined the bridge cannot carry legal truck loads.

ITD Bridge Asset Management has reviewed the **two bridges** pertaining to this request and has determined they will safely support the 129,000-pound truck load, provided the truck's axle configuration conforms to legal requirements. To review load rating data for each of the bridges, see the Bridge Data chart below.

## Materials Section Review

The Idaho Transportation Department's 129,000 pound pilot project report to the Idaho State Legislature in 2013 states, "For pavements, axle weight is a more significant determinant of pavement damage than gross vehicle weight. Truck weight limits that allow a higher GVW distributed over more axles do not necessarily lead to higher pavement costs and can even produce savings." Based on the increased number of axles required for 129,000 pound vehicles to maintain legal axle weights, the equivalent single axle loads (ESAL) for 129,000 pound vehicles are lower than for 80,000 pound and 105,500 pound vehicles. The implementation of the 129,000 pound configuration also reduces the number of truck trips compared to performing the same work with 80,000 or 105,000 pound trucks. The reduction in truck traffic further reduces the pavement wear. Therefore, for this section of roadway, our assessment is the increased vehicle weight with a corresponding increased number of axles will reduce loads per axle compared to 80,000 or 105,500 pound vehicles and thereby produce lower loads on the road surface and subsurface resulting in equal or lesser damage.

## ITD District 5 Evaluation

This segment has been evaluated and the District recommends proceeding.

District 5 has evaluated the roadway characteristics, pavement condition, and traffic volumes on SH-89 between milepost 41.17 – 44.24 in response to the request to make this segment a 129,000-pound trucking route. The District has found no concerns with this action and recommends proceeding. Details of the evaluation are provided below.

## Roadway Characteristics

This section of road is a rural principal arterial from MP 41.17 – 44.24. The roadway geometry is outlined in the table below.

**Table 1. SH-89 Roadway Geometry**

	THROUGH LANES	TWO-WAY LEFT TURN LANE (TWLTL)	SHOULDER	PARKING LANE
<b>MP 41.17 – 44.24</b>	2 – 1 each direction	No (Turn bays are present)	Yes	No
	12'	-	5'	-

**Pavement Condition**

The road is asphalt pavement and is in good to fair condition and is not deficient in cracking, roughness, or ruts. This section has received multiple seal coats in the past 20 years. It was reconstructed in 1994. Another seal coat is scheduled for 2017. Spring breakup limits do not pertain to this section at this time.

**Table 2. 2015 TAMS Visual Survey Data**

	PAVEMENT TYPE	DEFICIENT (YES/NO)	CONDITION STATE	CRACKING INDEX	ROUGHNESS INDEX	RUT AVERAGE (IN)
<b>MP 41.17 – 42.91</b>	Flexible	No	Good	4.8	3.12	0.12
<b>MP 42.91 – 43.42</b>	Flexible	No	Fair	4.7	2.79	0.11
<b>MP 43.42 – 44.24</b>	Flexible	No	Fair	4.8	2.85	0.07

**Traffic Volumes**

The speed limit of the highway is 65 mph. There is no stop lights in this segment. The traffic volumes are provided below.

**Table 3. 2016 Traffic Volumes**

	AADT	CAADT	% TRUCKS
<b>MP 41.17 – 44.24</b>	1100	160	15

**Truck Ramps**

Due to the flat nature of this segment, no runaway truck ramps exist.

**Port of Entry (POE)**

The POE maintains no rover sites on this short section of highway, however they do have one not far from this location at approximately MP 40.47 on US-89.

**Highway Safety Evaluation**

This US-89 segment has no Non-Interstate High Accident Intersection Location (HAL) and no HAL Clusters.

Analyses of the 5-year accident data (2011-2015) shows there were a total of 8 crashes involving 8 units (0 fatalities and 2 Injuries) on US-89 between MP 41.17 and MP 44.24 of which no crashes involved a tractor-trailer combination. Implementation of 129,000 pound trucking is projected to reduce truck traffic on this route.

**Additional Data:*****Bridge Data:***

**Route Number:** US 89  
**Department:** Bridge Asset Management  
**Date:** 7/26/2016

<b>Route</b>	<b>From:</b>	US 89 just West of SH 61 Junction
	<b>Milepost:</b>	41.17
	<b>To:</b>	US 89/WY State Line
	<b>Milepost:</b>	44.24

<b>Highway Number</b>	<b>Milepost Marker</b>	<b>Bridge Key</b>	<b>121 Rating<sup>a</sup> (lbs)</b>
89	41.02	16726	328,000
89	43.19	16731	240,000

<sup>a</sup>: The bridge is adequate if it has a rating value greater than 121,000 pounds or is designated as "OK EJ" (okay by engineering judgment).