

Wisconsin - 40 CFR 280.12 Public Record Statistics

Statistics apply to Federally Regulated facilities only

Statistics apply to October 1 2023 - September 30 2024

Item No	Measure as of 10/1/2024	Count
1	Total Petroleum USTs (In use, TOS, Closed, Abandoned) (UST-1)	86593
2	Total Petroleum USTs Closed (closed by removal, closed in place) (UST-2)	73178
3	Number of USTs closed by removal	70163
4	Total hazardous substance USTs (in use, TOS or closed) (UST-3)	910
5	Total Closed hazardous Substance UST Systems (UST-3a)	859
6	Number of UST installed since 12/22/1988	80933
7	Total UST facilities (in use or TOS) assigned for inspection	3601
8	Total USTs (in use or TOS) assigned for inspection	11794
9	Number of on-site UST Facility compliance inspections to date (UST-7)	2286
10	Number of USTs inspected to date	7316
11	Number of facilities with compliance issues	1193
12	Number of facilities with informal enforcement	10
13	Number of facilities with formal enforcement actions (order, 2nd notice, red tag)	842
14	Number of tanks with delivery prohibition	210
15	Facilities in Compliance with 2015 Spill Prevention Requirements	2240
16	Facilities in Compliance with 2015 Overfill Prevention Requirements	2082
17	Facilities in Compliance with 2015 Corrosion Prevention Requirements	2213
18	Facilities in Compliance with 2015 Release Detection Requirements	1241
19	Facilities in Compliance with 2015 Spill Prevention, Overfill Prevention, Corrosion Protection, and Release Detection Requirements	1171
20	Percentage of Facilities in Compliance with 2015 Spill Prevention Requirements (UST-9a)	98 %
21	Percentage of Facilities in Compliance with 2015 Overfill Prevention Requirements (UST-9b)	91 %
22	Percentage of Facilities in Compliance with 2015 Corrosion Protection Requirements (UST-9c)	97 %
23	Percentage of Facilities in Compliance with 2015 Release Detection Requirements (UST-9d)	54 %
24	Technical Compliance Rate: (Percentage of Facilities in Compliance with all of the 2015 Spill Prevention, Overfill Prevention, Corrosion Protection, and Release Detection Requirements) (UST-9e)	51 %
25	Percentage of Facilities in Compliance with Energy Policy Act Operator Training Requirements (UST-10)	91 %
26	Percentage of Facilities in Compliance with Financial Responsibility Requirements (UST-11)	83%
27	Percentage of Facilities in Compliance with Walkthrough Requirements (UST-12)	82 %

Compliance Measurement Statement:

The compliance rate is based on the combined performance measure of release detection and release prevention compliance for EPA Technical Compliance Rate (TCR) as determined by on-site inspections; including release detection for emergency generator or back-up tanks.

Reported Universe Statement:

The universe of tanks included in this reporting meet the ATCP 93 - Flammable and Combustible Liquids Administrative Code criteria that are "in-use" or "temporarily-out of-service" status; which include USTs 60 gallon capacity or larger and includes USTs that contain 1% by volume CERCLA substance.

Release Reporting:

The Wisconsin Department of Natural Resources (WDNR) has the statutory authority and is responsible for spill and release reporting. Statistics relating to UST related release statistics can be obtained at the following web site: <http://dnr.wi.gov/topic/Brownfields/Petro.html>

Site Specific Information May Be Obtained at the Following Web Site: [Internet Tank Search](#)

If you wish additional information regarding the statistical report or specific facilities you may request that information through the Freedom of Information Open Records Information process on-line at: [Public Information Request](#)